


MODEL NO. 10.223 Oval Strobe Quick Mount w/ Flash Back Shield



Flash tube rated 25 watts. Compact individual unit $2\frac{1}{4} \times 6\frac{1}{2}$ inches. Equipped with an 8 foot cable for easy routing and can mount anywhere. Available with grill, window or bumper mount brackets. Choice of RED, BLUE, AMBER, or CLEAR polycarbonate lenses. Requires remote power supply.

INTERNAL WINDOW MOUNTING INSTRUCTIONS:

CAUTION: The adhesive backed taped used to secure the light is a very aggressive contact tape that is virtually impossible to remove or relocate.

Before removing the cover film from the tape to expose the adhesive surface, hold the assembly against the glass surface and select the optimum location for your purposes. (For windshield mounting, to insure maximum light output, we suggest that the upper edge of the light be positioned *just below* the tinted area of the windshield.) Bend the mounting bracket as necessary to allow light assembly to be hung securely.

Once you have chosen the location and adjusted the mounting bracket as necessary, clean the mounting area with an alcohol swab. Place a strip of masking tape horizontally below the mounting location to act as a guide in the positioning of the light. **THEN AND ONLY THEN,** remove the cover film from the foam tape adhered to the mounting bracket. Place the bottom edge of the foam tape surface against the upper edge of the masking tape. Tilt the bracket upward to adhere the tape to the glass, and apply pressure to the back of the foam tape portion of the bracket to secure it and to remove any trapped air.

If the foam flash-shield wrinkles against the glass where it may cause possible interference with the light output, it may be trimmed with a pair of scissors to more closely match the slope of the glass.

The power supply may be mounted in any position, under the dash, in the trunk, under the seat, in the engine compartment or anywhere else in reach of the light connection cables.

Ground the black lead of the power supply to a known good ground. Connect the red, fused lead to a 12 DC source capable of supplying at least 10 amps through a switch.

Note: The lights must be connected to the power supply prior to switching on the power.

ALERTE SYSTEMS INC


901 W 10th Street / P.O. Box 586 / Cassville, MO 65625

Local & International Numbers:

U.S. and Canada Toll-Free Numbers:

Phone 417-846-2222 / Fax 417-846-2506

Phone 800-728-1536 / Fax 800-635-1536



ALERTE warrants each new product (except bulbs, strobe power supplies and strobe tubes) to be free from defects in material and workmanship for a period of two years from the date of purchase. During this warranty period, the obligation of ALERTE is limited to repairing or replacing, as ALERTE may elect, any part or parts, which after examination by ALERTE are determined to be defective, when they are delivered pre-paid. This limited warranty does not cover travel expense, the cost of specialized equipment for gaining access to the product, or labor charges for the removal and re-installation of the product.

ALERTE shall not be liable for incidental or consequential damages, including but not limited to: loss of use of vehicle, rental of substitute vehicle, loss of time, loss of work, inconvenience, transportation expenses, telephone, lodging, loss of revenue, loss of and/ or damage to personal property for or arising out of breach of any express or implied warranty of its products.

Use of lamp or other electrical load of wattage higher than installed or recommended by the factory, or use of inappropriate or inadequate wiring or circuit protection causes this limited warranty to become void. ALERTE will in no way be liable for any loss of profits or any indirect or consequential damages arising out of any such defect in material and workmanship whether loss is due to negligence or breach of warranty. This limited warranty does not apply to shipping damage, accident, alteration, tampering, misuse or abuse and unauthorized service.

This limited warranty is expressly in lieu of all other express or implied warranties, including the implied warranty of merchant ability and the implied warranty of fitness for a particular purpose, and of all other obligation or liabilities on the part of ALERTE. There are no warranties, unless expressed in authorized ALERTE literature, which extend beyond the description of the face hereof. No dealer, distributor, employee, or representative of the company is authorized to change this warranty in any way or to grant any other warranty.

PRODUCT RETURNS

If a product must be returned, contact our factory by calling 1-800-728-1536 to obtain a Return Authorization Number (RA) before you ship the product. Write the RA number clearly on the package and return it to ALERTE Systems International, Ltd., 901 West 10th Street, P.O. Box 586, Cassville, MO 65625. A packing slip should be included with all shipments listing the sender's name, address, daytime phone number and description of defect. Your product will be put in first-class operating condition or replaced with a new part, and returned pre-paid.